

Republic of the Philippines
DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS
OFFICE OF THE SECRETARY
 Manila

April 12, 2017

MEMORANDUM

FOR : **MARK A. VILLAR**
 Secretary
 This Department

This has reference to the memorandum dated March 22, 2017 from **OIC-Assistant Regional Director Alberto N. Gahid**, DPWH-CAR, forwarding the memorandum dated March 17, 2017 of District Engineer **Ireneo S. Gallato**, Lower Kalinga DEO relative to the request for modification on the project listed below:


LOCATION	Project Description		Physical Target/ Cost	
	UACS No.: 165003014500160		Original	New
	As per GAA	As modified		
Tabuk City, Kalinga	MFO 1 – National Road Network Services – Asset Preservation of National Roads – Rehabilitation/Reconstruction of National Roads with Slips, Slope Collapse, and Landslide – Secondary – Mt. Province Bdry – Calanan – Pinukpuk- Abbut Rd (Cagaluan-Calanan Sect) - Chainage 1347 – Chainage 1392, Chainage 2023 – Chainage 2035, Chainage – 5345 – Chainage 5376, Chainage 6670 – Chainage 6720, Chainage 10889 – Chainage 10904, Chainage 11753 – Chainage 11791, Chainage 13144 – Chainage 13349, Chainage 12598 – Chainage 12630, Chainage 1707 – Chainage 1772, Chainage 2319 – Chainage 2374, Chainage 4327 – Chainage 4347, Chainage 9964 – Chainage 10054, Chainage 2749 – Chainage 2774, Chainage 23388 – Chainage 23458, Chainage 18145 – Chainage 18173, Chainage 17620 – Chainage 17680 , Chainage 8876 – Chainage 9138, Chainage 11863 – Chainage 12063 <i>[CW1- Construction of Road Slope Protection Structure]</i> <i>[CW2- Rehab/Major Repair of Road Slope Protection Structure]</i>	MFO 1 – National Road Network Services – Asset Preservation of National Roads – Rehabilitation/Reconstruction of National Roads with Slips, Slope Collapse, and Landslide – Secondary – Mt. Province Bdry – Calanan – Pinukpuk- Abbut Rd (Cagaluan-Calanan Sect) - Chainage 1347 – Chainage 1392, Chainage 2023 – Chainage 2035, Chainage – 5345 – Chainage 5376, Chainage 6670 – Chainage 6720, Chainage 10889 – Chainage 10904, Chainage 11753 – Chainage 11791, Chainage 13144 – Chainage 13349, Chainage 12598 – Chainage 12630, Chainage 1707 – Chainage 1772, Chainage 2319 – Chainage 2374, Chainage 4327 – Chainage 4347, Chainage 9964 – Chainage 10054, Chainage 2749 – Chainage 2774, Chainage 23388 – Chainage 23458, Chainage 18145 – Chainage 18173, Chainage 18106 – Chainage 18146 , Chainage 8876 – Chainage 9138, Chainage 11863 – Chainage 12063 <i>[CW1- Construction of Road Slope Protection Structure]</i> <i>[CW2- Rehab/Major Repair of Road Slope Protection Structure]</i>	CW1-5,173m ² CW2-3,058m ²	CW1-5,193.30 m ² CW2-1,911.74 m ²
			Unit Cost ('000):	Unit Cost ('000):
			CW1-P5.210/m ² CW2-P2.933 /m ²	CW1-P5.329 /m ² CW2-P4.3313 /m ²
			Alloc. ('000):	Est. Cost ('000):
			P35,925	P35,925
			CW1- P26,955	CW1- P27,678
			CW2- P8,970	CW2- P8,247
Reason/s for Modification: Modification was sought due to increase in unit cost in consideration to the inclusion of concrete shoulders and barriers which are necessary for the safety of commuters/road users.				

Based on our evaluation on the submitted documents, the request for modification on the above-listed project was found in order, thus, approval is hereby recommended to the Honorable Secretary.


EUGENIO R. PIPO, JR.

Assistant Secretary for Luzon Operations

APPROVED/DISAPPROVED:


ROMEO S. MOMO, CESO I

Undersecretary

Officer-In-Charge

3.3 rbat/ERP/RSM

Department of Public Works and Highways
Office of the Secretary



WIN7E01439