Republic of the Philippines

DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS

EASTERN SAMAR

DISTRICT ENGINEERING OFFICE

Borongan City, Eastern Samar

Name of Procuring Entity : DPWH - ESDEO Request for Quotation (P.R. No.): 2025-02-0009

Revised on : Date: March 17, 2025

Standard Form/Title : REQUEST FOR QUOTATION Office/End-User : Construction/Maintenance Section

COMPANY NAME | ADDRESS | CONSTRUCTION OFFICE | CONSTRUCTION OFFICE | CONSTRUCTION | CON

TIN:

QTY.

1

1

1

1

4

2

2

20

2

2

1

2

1

2

1

1

1

tubes

Please quote your lowest price on the items(s) listed below, subject to the terms and Conditions stated below and submit your duly signed quotation personally or by your authorized representative **not later than 09:00 A.M.** of March 24, 202

in the return envelope attached herewith, to the BAC Secretariat, DPWH, Brgy. Alang-alang,

TERMS and CONDITIONS:

Item No.

1

2

3

4

5

6

8

9 10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25 26

27

28

29

30

31

32

33

34

TEL. NO./FAX NO.

- 1. All entries must be typewritten or legibly written.
- Delivery period within 30 c.d. upon receipt of the approved funded. Purchase Order (P.O.). Administrative penalties pursuant to Sec.69 of the Revised IRR-RA 9184 shall be imposed for non-delivery without valid reason.
- Warranty shall be for a minimum of three (3) months for supplies & materials; one year for Equipment; 3 years IT Equipment from date of acceptance by the end-user. (If applicable)
- 4. Mayor's Permit, PhilGEPS Reg. Number, Income/Business Tax Return and Omnibus Sworn Statement shall be attached upon submission of the quotation.
- 5. Legal documents must be certified true copy.

Cylinder Head Assembly

Connecting Rod Bearing

Timing Chains, Tensioner and Sprocket

Overhauling Gasket

Piston Assembly

Cylinder Liner

Main Bearing

Alternator Belt

Heater Plug

Piston Ring

Copper Paste

Parts Cleaner

Plastic Guage

Expansion Valve

Transmission Oil

Contact Cleaner

Silicon Gasket Maker

Valve Cover Gasket

Hose Clamp 1-1/4"

Plastic Steel Epoxy

Transmission Belt Housing Assembly

Transmission Control Shift Cable

Fuel Hose

Fan Belt

Automatic Transmission Fluid

Sand Paper

Brake Pad

Freon

Engine Support Aircon Belt

Enginer Oil

Coolant

Fuel Filter

- Bidders must quote for all of the items. Any erasure, correction or alteration made by the bidders in any of the items shall render the bid non-complying, hence, a ground for disqualification
- 7. The DPWH reserves the right to accept or reject any bid, to annul the bidding process, and to rejects all bids at any time prior to contract award without thereby incurring any liability to the affected bidder.
- Bidders shall submit original brochures showing certifications of the Product. (if applicable)
- 9. Please indicate the brand for each items being offered.(if applicable)
- 10. The approved budget ceiling for this procurement is Php: 679,090.00

Note: Submitted RFQ must be dult signed by the owner or Authorized Representative (SPA and or Secretary's Certificate enclosed)

For use in the Repair of Isuzu Elf with Plate No. SGM 424 (H2 362)

ITEMS & DESCRIPTION

For use in the Repair of Nissan Navara with Plate No. SGM 413(H1 5541)

/
JUDY C. ELGERA
BAC - Chairman

UNIT	UNIT PRICE	TOTAL PRICE
рс.		
set		
set set		
set		
pc.		
pcs		
рс		
set		
pcs.		
can		
set		
can		
pcs.		
pcs set		
kilo		
pc.		
liters		
liters		
can		
set		
pc.		
tubes		
pc.		
pcs.		
рс		

		T		•	
35	Copper Tube , 3/8	10	ft.		
36	Copper Tube, 1/4	15	ft.		
37	Fittings, 1/4	8	pcs.		
			_		
38	Fittings, 3/8	2	pcs.		
39	Carburator Assembly	1	pc.		
40	Bolt with Double Washer	2	pcs.		
41	Clutch Operating Assembly	1	рс		
42	Brake Master	1	рс		
43	Hose	5	meters		
44	Hose Clip	_			
		8	pcs.		
45	Repair Kit	1	set		
46	Pillow Block	2	pcs.		
	Welding Rod		_		
47	ÿ	2	box		
48	Cutting Disc	3	pcs.		
49	Grinding Stone	1	pc.		
50	Stud Bolt	1	pc.		
			_		
51	Lug Nut	2	pcs.		
52	Oil Seal	1	pc.		
	For use in the Repair of Isuzu Elf with Plate No. JAL 3528(H2 581)				
F2	Bolt	0	200		
53		8	pcs.		
54	Pillow Block	4	pcs.		
55	Wheel Cap	1	pc.		
56	Release Bearing	1		1	
		-	pc.,		
57	Rubber cup	5	pcs.		
	For use in the Repair of Caterpillar Payloader with DPWH No. I2 1473	Ī			
58	Hydraulic Hose with Fittings	1	pc.		
	,	' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '	ρυ.		
	For use in the Repair of Toyota Hi Lux with Temporary Plate No. 080106(H1 7385)]
	1 57 455 III tile Nepali of Toyota III Lux With Temporary Flate No. 900 100(11 7303)				
	Horn 191/	4	1	1	
59	Horn, 12V	1	set		
60	Wiper Blade	2	pcs.		
61	Mini Relay	1	pc.		
62	Relay Socket	1			
02		I	pc.		
	For use in the Repair of Mitsubishi Strada with Temporary Plate No. 080409(H1				
63	Secondary Clutch Assembly	1	pc.		
64	Crankshaft Oil Seal	1	· ·		
			pc.		
65	Stud Bolt With Nut	2	pcs.		
66	Cross Joint Bearing	3	pcs.		
67	Release Bearing	1	pc.		
68	Pressure Plate	1	pc.		
69	Clutch Disc	1	pc.		
	F				
	For use in the Repair of Fuso Canter with Temporary Plate No. 080401(H3 7005)				
70	Tire 195R14C	4			
70		1	pc.		
71	Clutch Operating Assembly	1	pc.		
	For use in the Repair of Isuzu Pick up with Plate No. SES 606 (H1 4864)				
70	Alternator Assembly	4			
72		1	pc.		
73	Fan Belt	1	pc.		
74	Rubber Cup	4	pcs.		
75	Valve Stern	1	pc.		
13		ı ı	ρс.		
	For use in the Repair of Isuzu Hi Lander with Plate No. SGM 417 (H1 7396)				
76	Horn Assembly, 12 V with Socket	1	pc.		
77	Relay 12V with Socket	2	pcs.		
	Headlight Socket		•		
78		2	pcs.		
79	Automotive wire	1	roll		
80	Electrical Tape	3	roll	<u> </u>	
81	Flasher Realy , 12V	1	pc.		
		-		1	
82	Signal Light	2	pcs.		
83	Headlight Valve	2	pcs.		
84	Single Contact Valve	1	pc.		
	For use in the Repair of Mitsibishi L200 with Plate No. SDN 790(H1 4863)	1	r · · ·		
					
85	Stop Light	2	pcs.		
86	Signal Light	2	pcs.		
87	Automotive wire # 12	1	roll		
88	Automotive wire # 16	1			
			roll		
89	Electrical Tape	4	roll		
90	Relay, 12V with Socket	2	pcs.	<u> </u>]
91	Flasher Realy with Socket	1	pc.		
	Headlight Socket	·			
00	n readilium SOCKEI	2	pcs.		
92			1		
92	For use in the Repair of Plate Compactor and Generator				
92		1	pc.		
93	For use in the Repair of Plate Compactor and Generator Fan Belt		pc.		
93 94	For use in the Repair of Plate Compactor and Generator Fan Belt Rubber Cup Bushing with Bolt	12	pcs.		
93 94 95	For use in the Repair of Plate Compactor and Generator Fan Belt Rubber Cup Bushing with Bolt Washer	12 24			
93 94	For use in the Repair of Plate Compactor and Generator Fan Belt Rubber Cup Bushing with Bolt	12	pcs.		
93 94 95	For use in the Repair of Plate Compactor and Generator Fan Belt Rubber Cup Bushing with Bolt Washer Ignition Coil	12 24	pcs.		
93 94 95 96	For use in the Repair of Plate Compactor and Generator Fan Belt Rubber Cup Bushing with Bolt Washer Ignition Coil For use of various Vehicles	12 24 1	pcs. pcs. pc.		
93 94 95	For use in the Repair of Plate Compactor and Generator Fan Belt Rubber Cup Bushing with Bolt Washer Ignition Coil For use of various Vehicles Fire Extinguisher, ABC	12 24	pcs.		
93 94 95 96	For use in the Repair of Plate Compactor and Generator Fan Belt Rubber Cup Bushing with Bolt Washer Ignition Coil For use of various Vehicles Fire Extinguisher, ABC For use in the Repair of Toyota Hi Lux with Plate No. SJV 933 (H1 5544)	12 24 1	pcs. pcs. pc.		
93 94 95 96	For use in the Repair of Plate Compactor and Generator Fan Belt Rubber Cup Bushing with Bolt Washer Ignition Coil For use of various Vehicles Fire Extinguisher, ABC For use in the Repair of Toyota Hi Lux with Plate No. SJV 933 (H1 5544)	12 24 1 30	pcs. pcs. pc.		
93 94 95 96	For use in the Repair of Plate Compactor and Generator Fan Belt Rubber Cup Bushing with Bolt Washer Ignition Coil For use of various Vehicles Fire Extinguisher, ABC	12 24 1	pcs. pcs. pc.		
93 94 95 96	For use in the Repair of Plate Compactor and Generator Fan Belt Rubber Cup Bushing with Bolt Washer Ignition Coil For use of various Vehicles Fire Extinguisher, ABC For use in the Repair of Toyota Hi Lux with Plate No. SJV 933 (H1 5544)	12 24 1 30	pcs. pcs. pc.		
93 94 95 96	For use in the Repair of Plate Compactor and Generator Fan Belt Rubber Cup Bushing with Bolt Washer Ignition Coil For use of various Vehicles Fire Extinguisher, ABC For use in the Repair of Toyota Hi Lux with Plate No. SJV 933 (H1 5544)	12 24 1 30	pcs. pcs. pc.		

(1.10000 111110 1000	al Amount in Words) TOTAL AMOUNT	
Purchase/delivery of spa equipment.	reparts for use of various DPWH vehicles and	TOTAL
above. If the space for Delivery Peri	Warranty Price Validity accepted your General Conditions, I / We quo	
Terms and Conditions specified by L		it means that I concur with the