

Republic of the Philippines DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS **OFFICE OF THE SECRETARY** 06 JUN 2018

Manila

MEMORANDUM

FOR

: Secretary MARK A. VILLAR

Secretary This Department

This refers to the Memorandum dated 25 of May 2018 of DPWH Region XI Regional Director ALLAN S. BORROMEO, CESO IV, endorsing the request of District Engineer Wilfredo G. Aguilar, Davao City DEO, request for the approval of the Modification of hereunder project for FY 2018 General Appropriation Act (GAA), to wit;

As per GAA/Original			As Modified		
		Project D	escription		
UACS No. 30020310 Project ID: P00230					
Convergence and Special Support Program			Convergence and Special Support Program		
Construction/ Improvement of Access Roads leading to Declared Tourism Destinations			Construction/ Improvement of Access Roads leading to Declared Tourism Destinations		
	oing Center-Madrazo F	St. leading to Marco Polo ruit Stands-Central Bank,	Ponciano StBangoy StJ Hotel-Aldevinco Shopping Brgy. 34D, Davao City		
Physical Target	Unit Cost (P'000)	Allocation (P'000)	Physical Target	Unit Cost (P'000)	Estimated Cos (P'000)
CW-1 Reconstruction from Paved to concrete: 2.520 lane kilometers	₱ 8,858.89/ lane km	Php 22,324.40	CW-1 Reconstruction to Concrete Pavement: 1.046 lane kilometers	₽ 17,436.76 /lane km	Php 18,237.80
			CW-2 Construction of Drainage Structure along Road: 269 lineal meters	₽ 15.19 /lineal meter	Php 4,086.60
EAO	-	Php 455.600	EAO	-	Php 455.600
	Total:	Php 22,780.00		Total:	Php 22,780.00

hence, bigger area to be rehabilitated;

The project includes sidewalk, curb and gutter, and reflectorized thermoplastic pavement markings, hence, higher unit cost; and

Additional component (Construction of Drainage Structure Along Road) since there is a need to upgrade/improve the drainage system up to outfall because it can no longer accommodate the volume of runoff waters especially during heavy downpour wherein the existing drainage structure is only 24" Ø with combination of open lined canal of 0.60m wide. Said type of work was made into a different component due to its substandard cost since the drainage structure involves pipe culverts having diameters of 910-1220 mm including manhole.

Based on our evaluation, the herein request is found in order, hence approval is hereby recommended.

RAFAEL **YABUT**

Senior Undersecretary Undersecretary for Regional Mindanao Operations

APPROVED/DISAPPROVED:

MARK A. VILLAR Secretary

RAFAPLO YABUT Senior Undersecretary Officer-In-Charge

Department of Public Works and Highways Office of the Secretary

