

April 6, 2018

## MEMORANDUM

:

FOR
-----

MARK A. VILLAR

Secretary This Department

This refers to the memorandum dated 22 March of **DPWH Region III Director ANTONIO V. MOLANO**, endorsing the request of **District Engineer GEORGE DC. SANTOS**, Nueva Ecija 1<sup>st</sup> District Engineering Office, for the approval of the **Modification** of the project under FY 2018 General Appropriation Act (GAA), to wit;

1400 N- 010100100		Project	Description		
UACS No. 310102100 Project ID: P0020012					
OO1: Ensure Safe and Reliable National Road System - Asset Preservation Program - Preventive Maintenance - Secondary Roads			OO1: Ensure Safe and Reliable National Road System - Asset Preservation Program - Preventive Maintenance – Sepandary Roads		
San Jose City-Rizał Rd via Pinili-Porais-Villa Joson (Palarilla) Rd - <b>K0161+905 - K0163+535,</b> K0163+ <b>545 -</b> K0165+ <b>128.7,</b> K0165+515 - K0166+480, K0172+091.70 - K0172+ <b>716,</b> K0173+508 - <b>K0174+689,</b> K0176+ <b>242.60</b> - K0176+841		San Jose City-Rizal Rd via Pinili-Porais-Villa Joson (Palarilla) Rd - K0160+-141.10 - K0160+000, K0160+100 - K0161+000, K0161+000 - K0161+104, K0161+309 - K0161+506.70, K0161+905 - K0163+522, K0163+531.70 - K0165+128.70, K0165+515 - K0166+480 K0172+091.70 - K0172+275, K0172+510 - K0172+716, K0173+508 - K0173+813, K0176+606 - K0176+841			
K0163+ <b>545</b> - K0165+17 K0172+091.70 - K0172-	8 <b>.7,</b> K0165+515 -   + <b>716,</b> K0173+508 -		<b>K0160+100 - K0161</b> <b>K0161+309 - K0161</b> K0163+ <b>531.70</b> - K016 K0172+091.70 - K017	+000, K0161+000 +506.70, K0161+9 55+128.70, K0165- 2+275, K0172+5	<b>) - K0161+104,</b> 005 - K0163 <b>+522,</b> +515 - K0166+480 <b>10 -</b> K0172+716,
K0163+545 - K0165+17 K0172+091.70 - K0172- K0176+242.60 - K0176 Type of Work/	8 <b>.7,</b> K0165+515 -   + <b>716,</b> K0173+508 -		K0160+100 - K0161 K0161+309 - K0161 K0163+531.70 - K016 K0172+091.70 - K017 K0173+508 - K0173+ Type of Work/	+000, K0161+000 +506.70, K0161+9 55+128.70, K0165- 2+275, K0172+5	<b>) - K0161+104,</b> 105 - K0163 <b>+522,</b> +515 - K0166+480 <b>10 -</b> K0172+716, - K0176+84 <u>1</u>
K0163+ <b>545</b> - K0165+17 K0172+091.70 - K0172- K0176+ <b>242.60</b> - K0176	8 <b>8.7,</b> K0165+515 - + <b>716,</b> K0173+508 - +841	• K0174+689,	K0160+100 - K0161 K0161+309 - K0161 K0163+ <b>531.70</b> - K016 K0172+091.70 - K017 K0173+508 - K0173+	+000, K0161+000 +506.70, K0161+9 55+128.70, K0165- 2+275, K0172+5 813, K0176+606 -	<b>) - K0161+104,</b> 105 - K0163 <b>+522,</b> +515 - K0166+480 <b>10 -</b> K0172+716, - K0176+84 <u>1</u>
K0163+545 - K0165+17 K0172+091.70 - K0172- K0176+242.60 - K0176 Type of Work/ Physical Target CW1 - Preventive Maintenance of Road: Asphalt Overlay/	<b>18.7,</b> K0165+515 - <b>+716,</b> K0173+508 - +841 Unit Cost ₱ 3.222M/	K0174+689, Allocation	K0160+100 - K0161 K0161+309 - K0161 K0163+531.70 - K0161 K0172+091.70 - K017 K0173+508 - K0173+ Type of Work/ Physical Target CW1 - Preventive Maintenance of Road: Asphalt Overlay/	+000, K0161+000 +506.70, K0161+9 55+128.70, K0165- 2+275, K0172+5: 813, K0176+606 - Unit Cost P 3.288M/	<b>- K0161+104,</b> 105 - K0163 <b>+522,</b> +515 - K0166+480 <b>10 -</b> K0172+716, - K0176+84 <u>1</u> <b>Estimated Cost</b>

MVUC in the year 2017 and implemented by this office in the same year, hence the change in station limits.
The decrease in physical target was due to different width of shoulder and the increase in price of emulsified

asphalt and bituminous concrete surface course, as per Construction Materials Price Data, 1st quarter 2018.





Page 2 of 2

Based on our evaluation, the submitted request for modification of the said project is in order; hence, approval hereof is recommended.

DIMAS S. SDGUILON Undersectedary for Regional Operations Regions I, II, III, IV-A, V & CAR

APPROVED/DISAPPROVED:

MARK A VILLAR Secretary

÷.

.

1.

.

2.4 mksa/AVS/ERP/DSS

