and a	Republic of the Philippines		once signed/initialed.
	DEPARTMENT OF PUBLIC WORKS AN OFFICE OF THE SECRET	Reference Number:	III-057
	Manila	Project ID:	P00603726LZ

MEMORANDUM

FOR : ROGER G. MERCADO Acting Secretary

This Department

This refers to the memorandum dated March 21, 2022 of **DPWH Region III Director Roseller A. Tolentino**, endorsing the request for Project Modification of **District Engineer Roderick A. Andal**, Aurora District Engineering Office requesting for the approval of the **Modification** of the project under FY 2022 General Appropriation Act (GAA), to wit;

As per GAA/Original			As Modified		
		Project D	escription		
UACS No. 3101031 Project ID: P006037	00901000 26LZ				
ORGANIZATIONAL OUTCOME 1: Ensure Safe and Reliable National Road System - Asset Preservation - Preventive Maintenance - Tertiary Roads A CastañedaMa Aurora-Sn Luis Rd - K0207 + 000 - K0207 + 147, K0207 + 417 - K0208 + 000,					
- K0207 + 147, K0)207 + 417 - KO		and the second	ITOTA-SIT LUIS RU	- 10207 + 030
	207 + 417 - K0 209 + 835 Unit Cost	208 + 000, Allocation	and the second	Unit Cost P ('000)	Estimated Cost P ('000)
- K0207 + 147, K0 K0209 + 726 - K0 Physical Target CW1 - Preventive Maintenance of Road, Asphalt Overlay:	207 + 417 - K0 209 + 835	208 + 000,	K0208 + 000	Unit Cost	Estimated Cost
- K0207 + 147, K0 K0209 + 726 - K0 Physical Target CW1 - Preventive Maintenance of Road, Asphalt Overlay: 1.654 Lane Km	0207 + 417 - K0 209 + 835 Unit Cost P ('000) ₽ 6,349.26 /	208 + 000, Allocation P ('000)	K0208 + 000 Physical Target CW1 - Preventive Maintenance of Road, Asphalt Overlay:	Unit Cost P ('000) ₽ 16,306.96 /	Estimated Cost P (`000) ₽ 10,501.68
- K0207 + 147, K0 K0209 + 726 - K0 Physical Target CW1 - Preventive Maintenance of Road, Asphalt Overlay:	0207 + 417 - K0 209 + 835 Unit Cost P ('000) ₽ 6,349.26 /	208 + 000, Allocation P ('000)	K0208 + 000 Physical Target CW1 - Preventive Maintenance of Road, Asphalt Overlay: 0.644 Lane Km	Unit Cost P ('000) ₽ 16,306.96 /	Estimated Cost P ('000)

- 1. Change in station limit due to decrease in physical target based on actual site validation and survey considering the shoulders to be overlaid.
- Official Road Condition Data shows K0208+000-K0209+000 is already asphalt overlaid and in good condition. Therefore, overlaying station K0208+000 backwards rather than overlaying intermittent stations with the allotted budget is preferable to improve the alignment overall pavement condition.

Based on our evaluation, the submitted request for modification of the said project is in order. Hence, the said request is hereby recommended for Secretary's consideration and approval.

ROBERTO R. BERNARDO Undersecretary for Regional Operations In Luzon (except NCR and Region IV-B)

APPROVED/DISAPPROVED:

ROGER G. MERCADO Acting Secretary

2.1 RAA/RAT/RRB

