



Republic of the Philippines
DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS
OFFICE OF THE SECRETARY
Bonifacio Drive, Port Area, Manila

MEMORANDUM

FOR : Secretary MARK A. VILLAR
This Department

This refers to the Memorandum dated February 12, 2020 of DPWH NCR Regional Director ADOR G. CANLAS, endorsing the request for approval of Modification of District Engineer GERARD P. OPULENCIA, North Manila District Engineering Office of the project under FY 2020 General Appropriation Act (GAA), to wit;

As per GAA/Original			As Modified		
Project Description					
UACS No. 300107200684000 Project ID: P00449032LZ					
Local Program			Local Program		
Local - Flood Control and Drainage - Flood Control Structures / Facilities - Local Infrastructure Program			Local - Flood Control and Drainage - Drainage / Protection Works - Local Infrastructure Program		
Bank Improvement (Steel Sheet Pile) along Estero de San Lorenzo, Brgy. 388, Manila City			Bank Improvement (Steel Sheet Pile) along Estero de San Sebastian, Brgy. 388, Manila City		
Physical Target	Unit Cost(P'000)	Allocation (P'000)	Physical Target	Unit Cost(P'000)	Allocation (P'000)
CW1 - Construction of Retarding Pond / Revetment and Riverwall 158,400 l.m.	P 309.46 l.m.	P 49,500,000	CW1 - Construction of Retarding Pond / Revetment and Riverwall 158,400 l.m.	P 309.46 / l.m.	P 49,500,000
EAO	-	P 500,000	EAO	-	P 500,000
	Total :	P 50,000,000		Total :	P 50,000,000
Justifications:					
• Modification is requested due to typographical error from Estero de San Lorenzo to Estero de San Sebastian, also there is no Estero de San Lorenzo at Barangay 388 only Estero de San Sebastian.					


Based on our evaluation, the submitted request for modification of the said project is found in order. Hence, the said request is hereby recommended for the Secretary's consideration and approval.

ROBERTO R. BERNARDO
Undersecretary for Operations
in Visayas, NCR and Region IV-B

APPROVED/DISAPPROVED:

MARK A. VILLAR
Secretary

Department of Public Works and Highways
Office of the Secretary



WIN0F06107