and Philippines -UBLIC WORKS AND HIGHWAYS ICE OF THE SECRETARY Manila

pril 20, 2020

## MEMORANDUM

:

MARK A. VILLAR

Secretary This Department

This refers to the memorandum dated 09 March 2020 of DPWH Region XIII Director POL M. DELOS SANTOS, endorsing the request of District Engineer HENRY CRUZ J. MARAPAO, Surigao Del Norte 2<sup>nd</sup> District Engineering Office, for the modification of the project under FY 2020 GAA, to wit;

UACS No. 3001112	As per GAA/Original		As Modified		
JACS No. 3001112		Project D	escription		
Project ID: P00444 Local Program – Nat Roads - Construction Improvement of Var Projects Rehabilitation / Reco Slips, Slope Collaps Coastal Road, Ca (1184+045, Brgy Cat	tional Roads and I / Repair / Rehabilit rious Infrastructur onstruction of Na se and Landslid bugo Section,	tional Roads with e, Surigao-Davao K1184+(-197) -	Local Program – Nati Roads - Construction / Improvement of Vari Projects Rehabilitation / Reco Slips, Slope Collapse a Road, Cabugo Section Cabugo, Claver, Suriga	nstruction of Nation K1183+947	including Local onal Roads with ao-Davao Coastal
Type of Work/	Unit Cost	Allocation	Type of Work/ Physical Target	Unit Cost	Estimated Cost
Physical Target CW1- <u>Rehabilitation</u> / Major Repair of Road Slope Protection Structure/	-	₽ 86,811.40M	CW1- Construction of Road Slope Protection Structure 2,959.01 sq.m.	₽ 29.338T/ sq.m.	₽ 86,811.40M
EAO	-	P 3,148.60M	EAO	-	₽ 3,148.60M
LAU	Total:	P 89.960M		Total:	P 89.960M
<u>Change of T</u> of Road Slop	pe Protection Stru	Rehabilitation / Maj	ed Program of Works an jor Repair of Road Slop needed work in this ro abilitated. K1183+947, conformir	ad section since, th	here is no existin
<u>Change of Tr</u> of Road Slop road slope pr Correction of Reference Po Adjustment	ppe of work from pe Protection Stru- rotection structure f start Station Lim sist (LPP) based of	Rehabilitation / Maj cture which is the to be repaired/reha it K1184+(-197) to	needed work in this ro	ad section since, the	here is no existin
<ul> <li><u>Change of Tr</u> of Road Slope pro- road slope pro- Correction of Reference Po- Adjustment of slope protect</li> <li>Based on our ev hence, approval</li> <li>DIMAS S. SOG Undersecretar</li> </ul>	vpe of work from pe Protection Stru- rotection structure f start Station Lim- bint (LRP) based o of end Station Lin- tion structure. valuation, the s hereof is recom- utpon, CESC for Regional Op	Rehabilitation / Maj octure which is the to be repaired/reha- it K1184+(-197) to an RBIA Database. mit K1184+045 to submitted reque mmended.	or Repair of Road Slop needed work in this ro abilitated. K1183+947, conformir K1184+065 to maximiz est for modification	ad section since, the group of the correct name the project limit	here is no existin aming of Location that requires roo
<ul> <li><u>Change of Tr</u> of Road Slope pro- road slope pro- Correction of Reference Po- Adjustment of slope protect</li> <li>Based on our ev hence, approval</li> </ul>	vpe of work from pe Protection Stru- rotection structure f start Station Lim- bint (LRP) based o of end Station Lin- tion structure. valuation, the s hereof is recom- utpon, CESC for Regional Op	Rehabilitation / Maj octure which is the to be repaired/reha- it K1184+(-197) to an RBIA Database. mit K1184+045 to submitted reque mmended.	or Repair of Road Slop needed work in this ro abilitated. K1183+947, conformir K1184+065 to maximiz est for modification	ad section since, the group of the correct name the project limit	here is no existin aming of Location that requires roa

WIN0G02955

2.3 mksa/LCA/AVS/DSS