



Republic of the Philippines
DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS
OFFICE OF THE SECRETARY
Manila

March 14, 2018

MEMORANDUM

FOR : **MARK A. VILLAR**
Secretary
This Department

This refers to the memorandum dated March 05, 2018 of Regional Director **DANILO E. VERSOLA, DPWH-Region V**, endorsing the request of District Engineer **RAINERO A. ZERDA, Masbate 1st DEO**, for the **modification** of project under the FY 2018 GAA, to wit:

As per GAA/Original			As Modified		
Project Description					
UACS No. 310205100202000 Project ID: P00201163LZ OO1: Ensure Safe and Reliable National Road System - Network Development Program - Construction of Missing Links/ New Roads			OO1: Ensure Safe and Reliable National Road System - Network Development Program - Construction of Missing Links/ New Roads		
Mandaon-Dayhangan Road, Masbate			Mandaon-Dayhagan Road, Masbate		
Type of Work/ Physical Target	Unit Cost	Allocation	Type of Work/ Physical Target	Unit Cost	Estimated Cost
CW1-Construction of Concrete Road/ 3.57 Lane Km	₱13.725 M /Lane Km	₱49.00M	CW1-Construction of Concrete Road/ 2.10 Lane Km	₱23.333M /Lane Km	₱49.00M
EAO	-	₱1.00M	EAO	-	₱1.00M
Total:		₱ 50.00M	Total:		₱ 50.00 M
Justification:					
• Typographical error. "Mandaon-Dayhangan Road" should be "Mandaon-Dayhagan Road, Masbate" • The increase in unit cost is due to the inclusion of additional hauling cost of materials brought by the insufficient supply of aggregates in the locality as per attached "Materials Hauling Analysis" since Masbate is an island province. • In anticipation of road widening in the near future, road side structures (e.g. slope protection and drainage) will be constructed at the edge of RROW limit.					

Based on our evaluation, the submitted request for modification of the said project is in order; hence, approval hereof is recommended.

DIMAS S. SOGUILON, CESO II
Undersecretary for Regional Operations
Regions I, II, III, IV-A, V & CAR

APPROVED/DISAPPROVED:



MARK A. VILLAR
Secretary

Department of Public Works and Highways
Office of the Secretary



2.4 IMM/LCA/AVS/DSS

WIN8G01891