	DEPARTMENT OF PUB OFFICE OF	of the Philippines 06.29.2022 LIC WORKS AND HIGHWAYS THE SECRETARY ive, Port Area Manila	4
	) SUBJECT:	Engineering Office (DEO)	)
NO Series of 2022	) 1/2022	Administering Abuyog-Silago Coasta Road (S00198LT), per D.O. 115 Series 2022, from Biliran DEO to Leyte 5th DEO in Region VIII	,

Pursuant to the Department Order (D.O.) Number 124, Series of 2016, to maintain the integrity of the information in the Road and Bridge Information Application (RBIA) and to ensure accuracy, consistency and proper information of its data, the inadvertently incorrect DEO mentioned in D.O. 115, S. 2022 to administer Abuyog-Silago Coastal Road (S00198LT) shall be corrected from **Biliran DEO** to **Leyte 5<sup>th</sup> DEO**, Region VIII.

This Order corrects the responsible DEO to administer the aforementioned road section stated in the previous issuance and shall take effect immediately.

**ROGER G. MERCADO** Acting Secretary

