



Republic of the Philippines
DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS
CAGAYAN 2ND DISTRICT ENGINEERING OFFICE
Abulug, Cagayan, Region II



Procuring Entity: DPWH-Cagayan 2nd DEO P.R. No.: 2025-01-021 ET.AL.
Standard Form/Title: Small Value Procurement (REQUEST FOR QUOTATION) P.R. Date: 1/21/2025, 1/21/2025
Revised on: Office/End User: Maintenance Section
COMPANY NAME:
ADDRESS:
Tel No./ Fax No:
T.I.N:

Please quote your lowest price on the item(s) listed, subject to the Terms and Conditions stated below and submit your quotation duly signed by your representative not later than 10:00 AM of March 10, 2025 to Procurement Unit, DPWH-Cagayan 2nd District Engineering Office, Libertad, Abulug, Cagayan and will opened on the same day at 10:30 AM

TERMS and CONDITIONS:

- 1 All entries must be type written or legibly written.
- 2 Delivery period within 30 working days upon receipt of the approved funded Purchase/Work Order. Administrative Penalties pursuant to Sec. 69 of the Revised IRR-RA9184 shall be imposed for non-delivery without valid reason.
- 3 Warranty shall be for a minimum of three (3) months for supplies and materials; One (1) year for Equipment from date of acceptance by the end user.
- 4 Price Validity shall be for a period of 30 calendar days.
- 5 PhilGEPS Registration Certificate / Mayor's Permit / Omnibus Sworn Statement / Income Tax Return shall be attached upon submission of the quotation.
- 6 Please indicate the brand for each items being offered
- 7 The approved budget ceiling for this procurement is Php 188,900.00
- 8 Service Vehicle (Isuzu Fuego M:2006, SFA 363/HI-4680 Isuzu Fuego M:2000, Toyota Hlux AOA 9972, Mitsubishi L300 H1-6314/B2-G381, M:2017, Isuzu Dmax H1-7433/XST 697.M:2004)

JESSELITO D. BASSIG
Engineer III
BAC - Chairperson

Item No	ITEM & DESCRIPTION	QTY	UNIT	UNIT PRICE	TOTAL PRICE
I	Clutch Lining (Isuzu Fuego M:2006)	-1-	pc		
II	Release Bearing (Isuzu Fuego M:2006)	-1-	pc		
III	Gear Oil #90 (Isuzu Fuego M:2006)	-3-	ltrs		
IV	Clutch Over (Isuzu Fuego M:2006)	-1-	set		
V	Disc Pad (Isuzu Fuego M:2006)	-2-	pairs		
VI	3SM Battery (Motolite) (Isuzu Fuego M:2006)	-1-	pcs		
VII	Ball Joint Upper (SFA 363/HI-4680 Isuzu Fuego M:2000)	-2-	pcs		
VIII	Ball Joint Lower (SFA 363/HI-4680 Isuzu Fuego M:2000)	-2-	pcs		
IX	Stabilizer Link (SFA 363/HI-4680 Isuzu Fuego M:2000)	-2-	pcs		
X	Stabilizer Bushing (SFA 363/HI-4680 Isuzu Fuego M:2000)	-2-	pcs		
XI	Strut Bar Bushing (SFA 363/HI-4680 Isuzu Fuego M:2000)	-4-	pcs		
XII	Tie Rod End RH/LH (SFA 363/HI-4680 Isuzu Fuego M:2000)	-1-	set		
XIII	Caliper Kit (SFA 363/HI-4680 Isuzu Fuego M:2000)	-1-	pc		
XIV	Fuego String Gear Box Repair Kit (SFA 363/HI-4680 Isuzu Fuego M:2000)	-1-	pc		
XV	Steering Hose Supply (SFA 363/HI-4680 Isuzu Fuego M:2000)	-1-	pc		
XVI	Air Cleaner (SFA 363/HI-4680 Isuzu Fuego M:2000)	-1-	pc		
XVII	Leaf Spring Bushing (SFA 363/HI-4680 Isuzu Fuego M:2000)	-8-	pcs		
XVIII	Swing Arm Dumper (SFA 363/HI-4680 Isuzu Fuego M:2000)	-2-	pcs		

Item No	ITEM & DESCRIPTION	QTY	UNIT	UNIT PRICE	TOTAL PRICE
XIX	Grease 500grams (SFA 363/HI-4680 Isuzu Fuego M:2000)	-1-	pc		
XX	Pinion Oil Seal (Transmission) (SFA 363/HI-4680 Isuzu Fuego M:2000)	-2-	pcs		
XXI	Wiper Blade (SFA 363/HI-4680 Isuzu Fuego M:2000)	-2-	pcs		
XXII	Oil Seal Axle (Transmission) (SFA 363/HI-4680 Isuzu Fuego M:2000)	-2-	pcs		
XXIII	Bearing (Transmission) (SFA 363/HI-4680 Isuzu Fuego M:2000)	-2-	pcs		
XXIV	Bearing (Toyota Hilux H1-5856/ZFK 301)(M:2006)	-2-	set		
XXV	Clutch Lining (Toyota Hilux H1-5856/ZFK 301)(M:2006)	-1-	pc		
XXVI	Clutch Cover (Toyota Hilux H1-5856/ZFK 301)(M:2006)	-1-	pc		
XXVII	Release Bearing (Toyota Hilux H1-5856/ZFK 301)(M:2006)	-1-	pc		
XXVIII	Battery (Toyota Hlux AOA 9972)(M:2014)	-1-	pc		
XXIX	Timing Belt (Toyota Hlux AOA 9972)(M:2014)	-1-	pc		
XXX	Drive Belt (Toyota Hlux AOA 9972)(M:2014)	-1-	pc		
XXXI	Tail Light (Toyota Hlux AOA 9972)(M:2014)	-2-	pc		
XXXII	13 x 24 Inner Tube & Flap (Road Grader N1-2302)	-2-	pcs		
XXXIII	23.5 x 25 Inner Tube & Flap (Wheel Loader L2-1651)	-2-	pcs		
XXXIV	245/70 R16 Tubeless Tire (Isuzu Dmax H1-7433/XST 697,M:2004)	-1-	pc		
XXXV	185 Rim 14 Tubeless Tire(Mitsubishi L300 H1-6314/B2-G381, M:2017)	-2-	pcs		
XXXVI	Engine Oil(Fully Synthetic)	-49-	ltrs		
XXXVII	Oil Filter	-7-	pcs		
	xxxx				
	xxx				
Total					

Brand and Model: _____

Delivery Period: _____

Warranty: _____

Price Validity: _____

After having carefully read and accepted your General Conditions, I/We quote on the item(s) at prices note above. If the space for Delivery period, Warranty and Price Validity are left blank, it means that I concur with the Terms and Conditions specified by DPWH.

Printed Name / Signature / Date _____

Tel. No. CP. No. & email address _____



Republic of the Philippines
DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS
CAGAYAN 2ND DISTRICT ENGINEERING OFFICE
Abulug, Cagayan, Region II



PURCHASE REQUEST

Appendix 60

Fund Cluster: _____

QMS-AS-SPMU Form No. 1 series of 2023

COA Circular No. 2015-07 s. 2015

Office/Section : Maintenance		PR No.: <u>2025-01-021</u> Responsibility Center Code : _____		Date: <u>1/21/2025</u>	
Stock/ Property No.	Unit	Item Description	Quantity	Unit Cost	Total Cost
I	pc	Clutch Lining	-1-	4,200.00	4,200.00
II	pc	Release Bearing	-1-	1,600.00	1,600.00
III	ltrs	Gear oil #90	-3-	350.00	1,050.00
IV	set	Clutch Over	-1-	4,900.00	4,900.00
V	pairs	Disc Pad	-2-	1,000.00	2,000.00
VI	pcs	3SM Battery (Motolite)	-1-	8,000.00	8,000.00
		nothing follows			
					21,750.00
Purpose: For use of service vehicle SFA 767/H1-4897(Isuzu Fuego M:2006) assigned in the Maintenance Section.					
Requested by: <u>JACKYLOU P. TORIDA</u> Signature : _____ Printed Name : _____ Designation : Chief, Maintenance Section					
Approved by: <u>EMMANUEL A. MANSIBANG</u> Signature : _____ Printed Name : _____ Designation : OIC-District Engineer					



PURCHASE REQUEST

Appendix 60

Fund Cluster: _____

QMS-AS-SPMU Form No. 1 series of 2023

COA Circular No. 2015-07 s. 2015

Office/Section : Maintenance		PR No.: <u>1025-02-070</u> Responsibility Center Code : _____		Date: <u>2/19/2026</u>	
Stock/ Property No.	Unit	Item Description	Quantity	Unit Cost	Total Cost
I	pcs	Ball Joint Upper	-2-	1,500.00	3,000.00
II	pcs	Ball Joint Lower	-2-	1,500.00	3,000.00
III	pcs	Stabilizer Link	-2-	1,300.00	2,600.00
IV	pcs	Stabilizer Bushing	-2-	400.00	800.00
V	pcs	Strut Bar Bushing	-4-	200.00	800.00
VI	set	Tie Rod End RH/LH	-1-	3,200.00	3,200.00
VII	pc	Caliper Kit	-1-	800.00	800.00
VIII	pc	Fuego Strng Gear Box Repair Kit	-1-	2,000.00	2,000.00
IX	pc	Steering Hose Supply	-1-	2,100.00	2,100.00
X	pc	Air Cleaner	-1-	2,000.00	2,000.00
XI	pcs	Leaf Spring Bushing	-8-	200.00	1,600.00
XII	pcs	Swing Arm Dumper	-2-	1,000.00	2,000.00
XIII	pc	Grease 500grams	-1-	500.00	500.00
XIV	pcs	Pinion Oil Seal (Transmission)	-2-	600.00	1,200.00
XV	pcs	Wiper Blade	-2-	600.00	1,200.00
XVI	pcs	Oil Seal Axle (Transmission)	-2-	500.00	1,000.00
XVII	pcs	Bearing (Transmission)	-2-	800.00	1,600.00
nothing follows					
					29,400.00
Purpose: For use of service vehicle SFA 363/H1-4680(Isuzu Fuego M:2000) assigned in the Maintenance Section.					
Requested by:		Approved by:			
Signature : 		Signature : 			
Printed Name : JACKYLOU P. TORIDA		Printed Name : EMMANUEL A. MANSIBANG			
Designation : Chief, Maintenance Section		Designation : OIC-District Engineer			



PURCHASE REQUEST

Appendix 60

Fund Cluster: _____

QMS-AS-SPMU Form No. 1 series of 2023

COA Circular No. 2015-07 s. 2015

Office/Section : Maintenance		PR No.: <u>2025-02-072</u> Responsibility Center Code : _____		Date: <u>7/19/2025</u>	
Stock/ Property No.	Unit	Item Description	Quantity	Unit Cost	Total Cost
I	set	Bearing (Toyota Hilux H1-5856/ZFK 301)(M:2006)	-2-	2,000.00	4,000.00
II	pc	Clutch Lining (Toyota Hilux H1-5856/ZFK 301)(M:2006)	1	4,200.00	4,200.00
III	pc	Clutch Cover (Toyota Hilux H1-5856/ZFK 301)(M:2006)	-1-	4,900.00	4,900.00
IV	pc	Release Bearing (Toyota Hilux H1-5856/ZFK 301)(M:2006)	-1-	2,500.00	2,500.00
V	pc	Battery (Toyota Hlux AOA 9972)(M:2014)	1	8,000.00	8,000.00
VI	pc	Timing Belt (Toyota Hlux AOA 9972)(M:2014)	1	2,500.00	2,500.00
VII	pc	Drive Belt (Toyota Hlux AOA 9972)(M:2014)	1	2,000.00	2,000.00
VIII	pc	Tail Light (Toyota Hlux AOA 9972)(M:2014)	2	5,500.00	11,000.00
IX	pcs	13 x 24 Inner Tube & Flap (Road Grader N1-2302)	2	6,000.00	12,000.00
X	pcs	23.5 x 25 Inner Tube & Flap (Wheel Loader L2-1651)	2	9,000.00	18,000.00
XI	pc	245/70 R16 Tubeless Tire (Isuzu Dmax H1-7433/XST 697,M:2004)	1	10,500.00	10,500.00
XII	pcs	185 Rim 14 Tubeless Tire(Mitsubishi L300 H1-6314/B2-G381, M:2017)	2	6,500.00	13,000.00
XIII	ltrs	Engine Oil(Fully Synthetic)	49	850.00	41,650.00
XIV	pcs	Oil Filter	7	500.00	3,500.00
		nothing follows			
					137,750.00
Purpose: For use of various Service Vehicles and Heavy Equipment assigned in the Maintenance Section.					
Requested by:		Approved by:			
Signature : 					
Printed Name : JACKYLOU P. TORIDA		EMMANUEL A. MANSIBANG			
Designation : <u>Chief, Maintenance Section</u>		<u>OIC-District Engineer</u>			