

## Republic of the Philippines Department of Public Works and Highways OFFICE OF THE DISTRICT ENGINEER

Batanes District Engineering Office Basco, Batanes



Name of Procuring Entity			Request for Quotation (P.R.		N0.) 2024-12-0141	
Revised on:			Date:		Dec. 5, 2024	
Standard Form/Title : REQUEST FOR QUOTATION			Office/End User: Maintenance Section			
COMI	PANY NAME:					
ADDE	RESS:					
TEL. NO./ FAX NO.:			TIN:			
Please qoute your lowest price on the item(s) listed below, subje						
and	submit your quotation duly signed by your representative no	ot later t	han 10:00	AM ofDec. 9, 2024	, 2024.	
1. 2. Ac de 3. for 4. 5. at ab 6. 7.	All entries must be <b>TYPE WRITTEN</b> or <b>ELIGIBLY WRITTEN</b> .  Delivery period within <b>45 C.D.</b> upon receipt of the approved funded Purolaministrative penalties pursuant to Sec.69 of the Revised IRR-RA 9184 shallivery without valid reason. <b>Warranty</b> shall be for a minimum of three (3) months for <b>SUPPLIES</b> & reQUIPMENT; three (3) years for <b>IT Equipment</b> from date of acceptar Price Validity shall be for a period of sixty (60) calendar days. <b>G-EPS Registration Certificate/Mayor's Permit/DTI/Latest Incontacted upon submission of the quotation.</b> For ABC exceeding the amount love, <b>Omnibus Sworn Statement</b> is required.  Bidders shall submit original brochures showing certificate of the product Please indicate the <b>BRAND</b> for each items being offered if applicable. The approved budget ceiling for this procurement is <b>P 202,531.49</b> .	MATERIAI nce by the e me Tax ret of Php 50,0	LS; one (1) yend-user.  Surn shall be 100.00 and	RODE	FRICK V. HORNEDO BAC Chairperson	
Item No.	ITEMS & DESCRIPTION	QTY.	UNIT	UNIT PRICE	TOTAL PRICE	
	DPWH No. L2-1518, Hitachi LX30-7 Loader					
1	Fan Belt, Part no. KBT1G52197010	2	pcs			
2	Shifting Control Cable, Part no. 302841-11120	2	pcs			
3	Oil Filter, Bosch 0986AF0122 or Part no. KBT1641432430	1	рс			
4	Fuel Filter, Part no. 301061-21130	1	рс			
5	Repair Kit-303831 99110- Hitachi, Bucket Cylinder	2	pcs			
6	Repair Kit-302831 99120- Hitachi, Boom Cylinder	2	pcs			
7	Steering Cylinder & Tie Rod, Part no. 335541-21000	1	assy			
8	Radiator, Part no. 336041-12000	1	assy			
	Wheel Leader FOTON Medal FLORES a 2012	-				
	Wheel Loader, FOTON, Model FL936F, s.2012		-			
	Engine: DEUTZ, Model WP6G125E22 DPWH No. L2-1480					
9	Air Booster Cylinder, PN.9D650-36A020000A0	1	unit			
10	Accelerator Cable, Foton Loader FL936f	1	set			
11	Fuel Filter, Hengst #70wk02	2	pcs			
12	Oil Filter, Sakura C-6204	2	pcs			
13	Wetcell Battery 12V 3SMF	2	pcs			
_	Fan Belt, AV13 x 1385La	2	pcs			
14				C. 35		
14						
14						
14						
14						
14	- 73					
14				TOTA	AL.	
Brand	and Model: ery Period :		Warranty Price Vali		NL.	

Printed Names/Signature/Date
Tel No./ Cellphone No. /Email Address