

Republic of the Philippines DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS **OFFICE OF THE SECRETARY** MANILA

May 05, 2021

## MEMORANDUM

TO

: Regional Director LORETA M. MALALUAN Regional Office No. II Tuguegarao City, Cagayan

## ATTENTION : OIC - District Engineer JOSE B. TOBIAS Isabela 2nd DEO

Transmitted herewith is the **duly approved** Request for Modification for the project under FY 2021 General Appropriation Act (GAA), viz:

Date Approved	As per GAA/Original		As Modified				
	Project Description						
	<ol> <li>Installation/ Application/ Construction of Road safety Devices in identified blackspots along Santiago-Tuguegarao Road K0382+061-K0383+065, K0383+080 - K0383+046, K0365+(-580)- K0365+420, K0408+350- K0409+345, K0392+424- K0393+424 and K0367+000-k0368+300</li> </ol>		Installation/ Application/ Construction of Road safety Devices in identified blackspots along Santiago-Tuguegarao Road K0382+061- K0383+065, <b>K0383+080 - K0384+046</b> , K0365+(-580)- K0365+420, K0408+350- K0409+345, K0392+424-K0393+424 and K0367+000-k0368+300				
	CW-1 – Road Safety: Road Signs – 94.00 Number of Signs	₱ 4,825,000	CW-1 – Road Safety: Road Signs – 94.00 Number of Signs	₱ 4,825,000			
	EAO	₱ 175,000	EAO	₱ 175,000			
	Total	₱ 5,000,000	Total	₽ 5,000,000			

In this regard, please be reminded that a **project can only be modified once** as prescribed under the FY 2021 GAA, and all approved modifications **shall be posted in the DPWH website within five (5) days from receipt thereof.** Failure to comply with this requirement shall be meted with appropriate sanctions.

Please be guided accordingly.

RAFAEL ABUT Senior Undersecretary Undersecretary for Regional Operations Regions I, II, III, IV-A, V and CAR

Cc: Undersecretary MARIA CATALINA E. CABRAL, Ph.D., Information Management, Planning and PPP Services Assistant Secretary WILFREDO S. MALLARI, Regional Operations in Regions I,II,III,IV-A,V and CAR



2

Republic of the Philippines DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS **OFFICE OF THE SECRETARY** MANILA

FOR

MARK A. VILLAR

Secretary

Respectfully forwarded is the memorandum dated March 11, 2021 of Regional Director LORETA M. MALALUAN, DPWH-REGION II, endorsing the request of OIC-District Engineer JOSE B. TOBIAS, Isabela 2<sup>nd</sup> DEO for the modification of project under the FY 2021 GAA, to wit:

	per GAA/Origin	nal	As Modified		
<b>Project Descripti</b>	on				
	002111000630 00534636LZ	000			
Convergence and S	ipecial Support Pi	rogram	Convergence and Special Support Program		
Special Road Fund as per R.A. 11239	– Motor Vehicle S	Support Program	Special Road Fund – Motor Vehicle Support Program as per R.A. 11239		
Installation/ Application/ Construction of Road safety Devices in identified blackspots along Santiago- Tuguegarao Road K0382+061-K0383+065, <b>K0383+080 - K0383+046</b> , K0365+(-580)- K0365+420, K0408+350- K0409+345, K0392+424- K0393+424 and K0367+000-k0368+300			Installation/ Application/ Construction of Road safety Devices in identified blackspots along Santiago- Tuguegarao Road K0382+061-K0383+065, <b>K0383+080 - K0384+046</b> , K0365+(-580)- K0365+420, K0408+350- K0409+345, K0392+424- K0393+424 and K0367+000-k0368+300		
<b>Physical Target</b>	Unit Cost	Allocation (P)	<b>Physical Target</b>	Unit Cost	Estimated Cost
CW-1 – Road Safety: Road Signs – 94.00 Number of Signs	₱ 51,329.79 / signs	₱ 4,825,000	CW-1 – Road Safety: Road Signs – 94.00 Number of Signs	₱ 51,329.79 / signs	₱ 4,825,000
EAO	-	₱ 175,000	EAO		₱ 175,000
Total: ₱ 5,000,000				Total:	₱ 5,000,000

## Justification:

- Change in stationing from K0383+080-K0383+046 to K0383+080-K0384+046 derived from Accident Black Spot Report (ABI-II-20-FEB).
- No change in unit cost and physical target.

Based on our evaluation, the submitted request for modification of the said project is in order; hence, approval hereof is recommended.

RAFAEDCAYABUT

Senior Undersecretary Undersecretary for Operations In Regions I, II, III, IV-A, V and CAR

APPROVED/DISAPPROVED:

MARK A. VILLAR Secretary

2.1 ETP/LTR

Department of Public Works and Highways Office of the Secretary WIN1C03755