	Min.	1
54	नगा	12
2	me	15
-	N.	

0, .

Republic of the Philippines DEPARTMENT OF PUBLIC WORKS AND HIGHWAY OFFICE OF THE SECRETARY

Reference Number:

17-055

Project ID:

P00343609MN

Manila

August 05, 2019

MEMORANDUM

FOR .. This Department Secretary MARK A. VILLAR

This refers to the memorandum dated 01 August 2019 of **DPWH Region IX Director CAYAMOMBAO D. DIA**, endorsing the request of **District Engineer AMINODIN P. MANIRI**, Zamboanga del Sur 2nd DEO for the **modification** of the project under FY 2019 GAA, to wit;

		yawan.	Typographical error. Bacawayan should be Bacayawan.	cal error. Bacaway	Justification: • Typographi
₽ 2.00 M	Total:		₽ 2.00 M	Total:	
₽ 20.00 T	1	EAO	₽ 20.00 T	I	EAO
₽ 1.98 M	₽ 1.98 M / Bldg.	CW1- Construction of Multi Purpose Building 1 Bldg.	₽ 1.98 M	₽ 1.98 M / Bldg.	CW1- Construction of Multi Purpose Building 1 Bldg.
Estimated Cost	Unit Cost	Type of Work/ Physical Target	Allocation	Unit Cost	Type of Work/ Physical Target
(Hall), Bacayawan,	ti-Purpose Building nga del Sur	Construction of Multi-Purpose Building (Hall), Bacayawap, Dimataling, Zamboanga del Sur	(Hall), Bacawayan,	i-Purpose Building (nga del Sur	Construction of Multi-Purpose Building (Hall), Bacawayan, Dimataling, Zamboanga del Sur
ther Structures - cture Program	Buildings and Ot ties - Local Infrastruc	Local Program - Buildings and Other Structures Multipurpose / Facilities - Local Infrastructure Program	her Structures - ucture Program	Buildings and Ot ties - Local Infrastru	Local Program - Buildings and Other Structures Multipurpose / Facilities - Local Infrastructure Program
				211281000 3669MN	UACS No. 300104211281000 Project ID: P00343669MN
		Project Description	Project D		
こう こう うちまたい ないのない	AS Modified			As per GAA/Original	AS

Based on our evaluation, the submitted request for modification of the said project is in order; hence, approval hereof is recommended.

APPROVED/DISAPPROVED: Undersecretary Secretary DIMAS S. SOC MARK A. VILLAR or DN, CESO I Regional Operations in Mindanao Department of Public Works and Highways Office of the Secretary WIN9G02743

2.3 IMM/LCA/AVS/DSS