



Republic of the Philippines
DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS
OFFICE OF THE SECRETARY
Manila

MEMORANDUM

FOR : MARK A. VILLAR
Secretary

This has reference to the herein Memorandum dated 19 April 2021 of **DPWH Region IV-B OIC Director YOLANDA L. TANGCO, CESO IV**, requesting for the approval of the **Modification** of the project under FY 2021 general Appropriation Act (GAA), to wit:

As per GAA/Original			As Modified		
Project Description					
UACS No. 310306100186000 Project ID: P00516214LZ					
Ensure Safe and Reliable National Road System			Ensure Safe and Reliable National Road System		
Bridge - Construction of New Bridges			Bridge - Construction of New Bridges		
Lumintao Bridge (Parallel Bridge) along Mindoro West Coastal Rd			Lumintao Bridge (Parallel Bridge) along Mindoro West Coastal Road		
Physical Target	Unit Cost (₱'000)	Allocation (₱'000)	Physical Target	Unit Cost (₱'000)	Estimated Cost (₱'000)
CW1- Construction of Parallel Bridge: 0 Square meters (sq.m.)	₱ 0/ Square meters (sq.m.)	₱ 173,700.00	CW1- Construction of Parallel Bridge: 1,717.20 Square meters (sq.m.)	194 Ln. ₱ 101.15/ Square meters (sq.m.)	₱ 173,700.00
EAO	-	₱ 6,300.00	EAO	-	₱ 6,300.00
Total:		₱ 180,000.00	Total:		₱ 180,000.00
Justification:					
1. Modification is necessary to reflect the physical target of 1,717.2 sq.m. of parallel bridge since no physical target reflected in GAA2021, wherein its design for concrete piles and prestressed structural concrete members with allocated fund for the project is only sufficient.					
2. Attached is the certification of reasonableness of unit cost dated April 19, 2021.					

Based on our evaluation, the submitted request for modification of the said project is found in order. Hence, the said request is hereby recommended for the Secretary's consideration and approval.

ROBERTO R. BERNARDO, CESO I
Undersecretary for Operations
In Visayas, NCR and Region IV-B

APPROVED / DISAPPROVED

MARK A. VILLAR
Secretary

2.6 APJ/RRB

Department of Public Works and Highways
Office of the Secretary



WIN1F06704