



Repair/Maintenance of DPWH Building, Zamboanga City 2nd DEO Building, Maintenance and Planning Building (Maintenance Section) Phase II, MCLL Highway, Divisoria, Zamboanga City

FORM POW-2015-01B-00

MINIMUM EQUIPMENT REQUIREMENT							
No.	Equipment Description	Capacity	Number of Equipment	No.		Capacity	Number of Labor
1	JackHammer		2	1	Construction Foreman		1
2				2	Skilled Labor		3
3				3	Labor		6
4				4	Safety Officer		1
5				5	Health Personnel		1
6				6			
7				7			
8				8			
9				9			
10				10			
11				11			
12				12			
13				13			
14				14			
15				15			
16				16			
17				17			
18				18			
19				19			
20				20			
21				21			
22				22			
23				23			
24				24			
25				25			
26				26			
27				27			
	TOTAL		2		TOTAL		12