



Republic of the Philippines
DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS
LEYTE 4TH DISTRICT ENGINEERING OFFICE
Ormoc City, Region VIII



Name of Procuring Entity :	DPWH 4TH DEO	Request for Quotation (P. No.):	2025-02-023
Revised on :		Date:	February 26, 2025
Standard Form/Title :	REQUEST FOR QUOTATION		
COMPANY NAME :	Office/End-User :		
ADDRESS :	VICTOR S. SUPILICO, III		
TEL NO. / FAX NO. :			

Please quote your lowest price or the item(s) listed below, subject to the Terms and Conditions stated below and submit your quotation duly signed by your representative not later than **MAR 24 2025 9:00 a.m. in the return envelope attached herewith, to the Procurement Office, DPWH, 4TH DEO, Ormoc City, Leyte.**

TERMS AND CONDITIONS :

- All entries must be typewritten or legibly written.
- All pages must be duly signed.
- Delivery period within 45 C. D. upon receipt of the approved funded Purchase Order (P. O.). Administrative penalties pursuant to Sec. 69 of the Revised IRR-RA 9184 shall be for a minimum for non-delivery without valid reason.
- Warranty shall be for a minimum of three (3) months for supplies & materials; one year for Equipment from date of acceptance by the end-user.
- Price validity shall be for a period of sixty (60) calendar days.
- G-PPS Registration number & Mayor's Permit/Business Permit & Omnibus Sworn Statement shall be attached upon submission of the quotation.
- Bidders shall submit original brochures showing certifications of the product if applicable.
- Quotations to be submitted by Lot
- Please indicate the brand for each item being offered.
- Eco-friendly supplies/equipment
- The approved budget ceiling for this procurement is **P78,966.18**
- Quotations submitted thru mail & Fax will not be accepted.

JOEL V. PEREZ
BAC Chairman
Engineer III

Item No.	ITEM / DESCRIPTION	QTY.	UNIT	UNIT PRICE	TOTAL PRICE
1	Repair and Replacement of damaged parts Steering system of Service Vehicle TOYOTA HILUX: CS#: YU-8416 BOE No.H1-8446: Prop No: 1060601000-C12MV002-2016-12-01101101-0405 (1hr) Replace Clip Pin Hole, Hold (4pcs) Pin (3pcs) Toyota Genuine Bactaklenz 7ml (10pcs) Rags PMS (2pcs) Brake Stop Squel Kit (4.5hrs) Replace Boot Steering Rack LH RH (2pcs) Boot Set, Steering R (2pcs) End Sub-Assy, Tie Rod (3hrs) Replace Stabilizer Link RH LH (1pc) Link Assy, FR Stabilizer LH (1pc) Link Assy, FR Stabilizer RH (1pc) Replace Brake Drum RH LH (2pcs) Drum, Brake (3.3hrs) Wheel Alignment Genuine parts compatible to TOYOTA HILUX	1	Lumpsum		
2	Repair and Replacement of damaged parts Steering system of Service Vehicle TOYOTA HILUX: Plate No. HAA-9392; BOE No.H1-8433: Prop No: 1060601000-C12MV002-2018-01-01101101-0245 (2hrs) Replace Stabilizer Link LH (1pc) Link Assy, FR Stabilizer (2hrs) Perform Wheel Balance (60pcs) Stick on Wheel Weight 3oz Regular Bar90 (3hrs) Replace Idle Tensioner Pulley (1pc) Tensioner Assy, V-R1 (1pc) Pulley Sub-Assy, Idle (3.3hrs) Perform Complete Wheel Alignment Genuine parts compatible to TOYOTA HILUX *****NOTHING FOLLOWS*****	1	Lumpsum		
Grand Total					

FOR THE PROCUREMENT OF REPAIR AND REPLACEMENT OF DAMAGED PARTS FOR PLATE NO. YU-8416 & HAA-9392 @DPWH LEYTE 4TH DEO

Brand and Model	Warranty
Delivery Period	Price Validity

After having carefully read and accepted your General Conditions, I / We quote you on the item(s) at price note above. If the space for Delivery Period, Warranty and Price Validity are left blank, it means that I concur with the Terms and Conditions specified by DPWH.

Printed Name / Signature / Date
Tel. No. / Callphone No. / E-mail Address