| Republic of the Philippines | | | | | | | | |
|---|--|---|------------------|---------------|-------------------------------|---------------------|--|--|
| DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS SOUTH COTABATO 1ST | | | | | | | | |
| DISTRICT ENGINEERING OFFICE | | | | | | | | |
| | REGIONAL OFFICE XII | | | | | | | |
| | | Tindalo St., Balite, Brgy. Lagao, (| General Sant | os City | | | | |
| Name of Procuring Entity : DPWH So. Cot. 1ST , DEO, GSC | | | Request fo | r Quotatio | n PR No: | 2024-06-145-041 | | |
| Revise | d on : | | | | | June 20, 2024 | | |
| Standa | ard Form/Title : REQUEST FO | R QUOTATION (Small Value Proce | irement) | Office/En | d - User : | Maintenance Section | | |
| сом | PANY NAME : | | | | | | | |
| | ADDRESS : | | | | | | | |
| | NO./FAX No. : | listed below. Subject to the Terms and Co | aditions stated | below and sul | TIN : | ion duly signed | | |
| | | .M. Of June 25, 2024 in the return envelo | | | | | | |
| of Publi | c Works and Highways South Cotaba | to 1st District Engineering Office, Tindal | St., Balite, Brg | y. Lagao, Ger | neral Santos City | • | | |
| | IS and CONDITIONS: htries must be typewritter or legibly wr | tten | 1 | | | | | |
| 2. Deliv | ery period within 20 CD upon receipt | of the approved funded Purchase | | | | | | |
| | P.O), Administrative penalties pursuar nall be imposed for non-delivery witho | | | | TEODY R. (Chief, Construc | | | |
| 3. Warr | anty shall be for a minimum of three (| 3) months for supplies & materials;one | | | BAC Chair | | | |
| | validity shall be for a period of sixty (6 | m date of acceptance by the end-user. i0) calendar days. | | | | | | |
| | S Registration Number/Mayor's Per e attached upon submission of the | mit/DTI & Omnibus Sworn Statement | | | | | | |
| 6. Bidde | ers shall submit original brochures of t | he product. | | | | | | |
| 1 | se indicate the brand for each items b approved budget ceiling for this procu | - | | | | | | |
| Item | | | <u>'-</u> | | | | | |
| No. | ITEMS & DESC | RIPTION | QTY | UNIT | UNIT PRICE | TOTAL PRICE | | |
| | Supply and Delivery of S operation of Maintenanc Cotabato 1st DEO, Gener | e Section of DPWH South | | | | | | |
| | TOYOTA HILUX (SKC-978 Engine No.: 2K07909294 | - | | | | | | |
| | Timing belt | | 1 | рс | | | | |
| | 7Pk fan belt | | 1 | рс | | | | |
| | Shock absorber front | | 2 | pcs | | | | |
| | Shock absorber rear | | 2 | pcs | | | | |
| | Air cleaner | | 3 | pcs | | | | |
| | Oil filter | | 3 | pcs | | | | |
| | Fuel filter | | 3 | pcs | | | | |
| | HUB BOLT/RIMBOLT | | 20 | pcs | | | | |
| | Tire patch 50mm | | 2 | box | | | | |
| | Rim 15 (5 holes) | | 1 | рс | | | | |
| | SUZUKI MULTICAB (H1-58) No.: F6A-5474900 | 20,) Year Model:2010, Engine | | | | | | |
| | Timing belt | | 1 | рс | | | | |
| | Fan belt | | 1 | pcs | | | | |
| | Shock absorber rear L&R | | 2 | pcs | | | | |
| | Brake pad front | | 1 | set | | | | |
| | Brake shoe rear | | 1 | set | | | | |

| Interfact of the second sec | High tension wire | 1 | set | |
|--|-------------------------------|---|------|--|
| Ignition coil 12V 1 pc 1 Puel pump fuel 1 pc 1 Puel filter 3 pcs 1 The patch S0mm 2 box 1 Ar cleaner 3 pcs 1 MAZDA Bongo (H1-S802, 122-604), Year Model: 2 pcs 1 MAZDA Bongo (H1-S802, 122-604), Year Model: 2 pcs 1 MAZDA Bongo (H1-S802, 122-604), Year Model: 2 pcs 1 MAZDA Bongo (H1-S802, 122-604), Year Model: 2 pcs 1 Shock absorber fort 1 pc< | | | | |
| Pud pump fuel1pc1Pud filter33pcs1Tre patch 50mm2box1Ar deaner33pcs1MAZDA Bongo (H1-5802, 122-604), Year Model: 2010, Engine No.: R277T8141pc1Timing belt1pc11Fan belt1pc11Shock absorber rear2pcs11Shock absorber rear3pcs11Alternator assentialy1assy11Alternator assentialy1ssey11Clutch cylinder1pc11Gov plug2pcs11Gov plug2pcs11Supersion arm upper (1 & R)2get11Supersion arm lower (1 & R)2get11Supersion arm lower (1 & R)2get11Supersion arm lower (1 & R)1get11Supersion arm lower (1 & R)2get11Supersion arm lower (1 & R)1get11Supersion arm lower (1 & R) <t< td=""><td></td><td></td><td>-</td><td></td></t<> | | | - | |
| Fuel filter33pcs1Tre patch S0mm2box1Ar deaner3pcs1MAZDA Bongo (H1-5802, 122-604), Year Model: 2010, Engine No.: R277T8141pcTiming belt1pc1Fan belt1pc1Shock absorber Front2pcs1Shock absorber Front3pcs1Oli filter3pcs1Oli filter3pcs1Oli filter3pcs1Gludt cylinder1pc1Gludt cylinder1pc1Gludt cylinder1pc1Suspension arm upper (L & R)2set1Suppension arm upper (L & R)1pc1Suppension arm upper (L & R)2set1Suppension arm upper (L & R)1pc1Suppension arm upper (L & | | | - | |
| Tre patch 50mm2baxIAr deaner3pcsIMAZDA Bongo (H1-S802, 122-604), Year Model: 2010, Engine No.: R277T8141pcITiming belt1pcIIFan bet1pcIIShock absorber Front2pcsIIShock absorber Front3pcsIIOlf filter3pcsIIIOlf filter3pcsIIIOlf filter3pcsIIIOlf filter1assyIIIOlf filter1pcIIIOld filter1pcsIIIOld filter1pcsIIIOld filter1pcsIIIOld filter1pcsIIIOld filter1pcsIIIOld filter1pcsIIIOld filter1pcIIIOld plg2pcsIIISuspension am upper (L & R)1pcIISuspension am upper (L & R)IiiISuspension am upper (L | | | - | |
| Air deaner3pcsImageMAZDA Bongo (H1-5802, 122-604), Year Model: 2010, Engine No.: R277T814ImageImageTiming belt1pcImageFan belt1pcImageShock absorber Front2pcsImageShock absorber Front2pcsImageShock absorber rear2pcsImageRuel filter3pcsImageOll filter3pcsImageAkrenator assembly1assyImageAir deaner3pcsImageClutch cylinder1pcImageGlow plug2pcsImageSuspension arm upper (L&R)2setImageSupension arm lower(L&R)1pcImageSupension arm lower(L&R)1pcImageSupension arm lower(L&R)1pcImageSupension arm lower(L&R)1pcImageSupension arm lower(L&R)1pcImageSupension arm lower(L&R)1pcImageSupension arm lower(L&R)1pcImageBrake pad front1pcImageBrake shoe rear1setImageIghthension wire1setImageBrake shoe rear1pcImageIghthen con 12V1pcImageIghthen con 12V1pcImageIghthen con 12V1pcImageIghth | | 3 | pcs | |
| MAZDA Bongo (H1-5802, 122-604), Year Model: 2010, Engine No.: R277T814Image of the second se | Tire patch 50mm | 2 | box | |
| 2010, Engine No.: R277B14 Image No: R27B14 Image No: R27B | | 3 | pcs | |
| Fan belt1pc1Shock absorber Front2pcs1Shock absorber rear2pcs1Fuel filter3pcs1Oil filter3pcs1Alternator assembly1assry1Air deaner3pcs1Clutch cylinder1pc1Tire patch 50mm2box1Suspension arm upper (L & R)2set1Suspension arm lower (L & R)2set1Timing belt1pcs1Timing belt1pcs1Fan belt1pcs1Brake pad front1pcs1Brake pad front1set1Inition cap1set1Infibition cap1pc1Infibition cal 12V1pc1Infibition cal 12V1pc1Infibition cal 12V1pc1Infibition cal 12V1 <td></td> <td></td> <td></td> <td></td> | | | | |
| Shock absorber Front2pcs1Shock absorber rear2pcs1Fuel filter3pcs1Oll filter3pcs1Alternator assembly1assy1Air cleaner3pcs1Clutch cylinder1pc1Tire patch 50mm2box1Suspension arm upper (L & R)2set1Suspension arm lower(L & R)2set1Tirning belt1pc1Fan belt1pcs1Shock absorber rear L & R2pcs1Brake pad front1set1Ight tension wire1set1Ight tension wire1set1Ight tension wire1set1Ight tension wire1set1Ight tension wire1pc1Ight tension wire1 | Timing belt | 1 | рс | |
| Shock absorber rear 2 pcs Image: state | Fan belt | 1 | рс | |
| Fuel filter 3 pcs Image: State of the state of | Shock absorber Front | 2 | pcs | |
| Oil filter3pcsImage: second s | Shock absorber rear | 2 | pcs | |
| Alternator assembly 1 assy Image: Constraint of the system of the | Fuel filter | 3 | pcs | |
| Air cleaner3pcs1Clutch cylinder1pc1Tire patch 50mm2box1Glow plug2pcs1Suspension arm upper (L & R)2set1Suspension arm lower(L & R)2set1SuzUKI MULTICAB SKB-466 (H1-526) YEAR MODEL:2010, ENGINE NO.: F6A64308781pcTiming belt1pc1Fan belt1pcs1Shock absorber rear L & R2pcs1Brake pad front1set1Ight tension wire1set1Ight tension wire1set1Ight tension wire1pc1Ight tension wire1pc1< | Oil filter | 3 | pcs | |
| Clutch cylinder1pcTire patch 50mm2boxGlow plug2pcsSuspension arm upper (L & R)2setSuspension arm lower(L & R)1pcSuspension arm lower(L & R)1pcFan belt11pcsShock absorber rear L & R2pcsBrake pad front1setBrake pad front1setIghtension wire1setJetribution cap1pcIgnition cil 12V1pcFuel pump fuel1pcFuel filter3pcsFuel filter3pcsTire patch 50mm2boxHont44 | Alternator assembly | 1 | assy | |
| Tire patch 50mm2boxImage: constraint of the sector of the | Air cleaner | 3 | pcs | |
| Glow plug2pcsImage: constraint of the section of the | Clutch cylinder | 1 | рс | |
| Suspension arm upper (L & R) 2 set Image: Set of the set | Tire patch 50mm | 2 | box | |
| Suspension arm lower(L & R)2setSUZUKI MULTICAB SKB-466 (H1-526) YEAR MODEL:2010, ENGINE NO.: F6A64308781pcTiming belt1pcFan belt1pcsShock absorber rear L & R2pcsBrake pad front1setHigh tension wire1setDistribution cap1pcFuel pump fuel1pcFuel filter3pcsTire patch 50mm2box | Glow plug | 2 | pcs | |
| SUZUKI MULTICAB SKB-466 (H1-526) YEAR MODEL:2010, ENGINE NO.: F6A6430878IITiming belt1pcIFan belt1pcsIShock absorber rear L & R2pcsIBrake pad front1setIBrake shoe rear1setIHigh tension wire1setIDistribution cap1pcIIgnition coil 12V1pcIFuel pump fuel1pcIFuel filter3pcsITire patch 50mm2boxI | Suspension arm upper (L & R) | 2 | set | |
| MODEL:2010, ENGINE NO.: F6A6430878IIIIITiming belt1pcsIII | Suspension arm lower(L & R) | 2 | set | |
| Fan belt1pcsImage: second sec | | | | |
| Image: Constraint of the section of | Timing belt | 1 | рс | |
| Image: constraint of the state of the sta | Fan belt | 1 | pcs | |
| Image: constraint of the section of | Shock absorber rear L & R | 2 | pcs | |
| High tension wire1setIDistribution cap1pcIIgnition coil 12V1pcIFuel pump fuel1pcIFuel filter3pcsITire patch 50mmIIII | Brake pad front | 1 | set | |
| Image: Constraint of the sector of the sec | Brake shoe rear | 1 | set | |
| Ignition coil 12V 1 pc Fuel pump fuel 1 pc Fuel filter 3 pcs Tire patch 50mm 2 box | High tension wire | 1 | set | |
| Fuel pump fuel 1 pc Fuel filter 33 pcs Tire patch 50mm 2 box | Distribution cap | 1 | рс | |
| Fuel filter 3 pcs Tire patch 50mm 2 box | Ignition coil 12V | 1 | рс | |
| Tire patch 50mm 2 box | Fuel pump fuel | 1 | рс | |
| | Fuel filter | 3 | pcs | |
| Air cleaner 3 pcs | Tire patch 50mm | 2 | box | |
| | Air cleaner | 3 | pcs | |

| MAZDA Bongo (H1-5817, SKX-747), Year Model:2006, Engine No.: R2676841 | | | |
|--|---|------|--|
| Timing belt | 1 | рс | |
| Fan belt | 1 | рс | |
| Shock absorber Front | 2 | pcs | |
| Shock absorber rear | 2 | pcs | |
| Fuel filter | 3 | pcs | |
| Alternator assembly | 1 | assy | |
| Oil filter | 3 | pcs | |
| Air cleaner | 3 | pcs | |
| Clutch cylinder | 1 | рс | |
| Tire patch 50mm | 2 | box | |
| Glow plug | 2 | pcs | |
| Ball joint upper | 2 | pcs | |
| Ball joint lower lower | 2 | pcs | |
| MITSUBISHI L300 (H1-6441/B0-J056), Year Model: 2017 Engine No.: 4D56AAR4546 | | | |
| Timing belt | 1 | set | |
| Fan belt (water pump) | 1 | рс | |
| Shock absorber front L & R | 2 | pcs | |
| Shock absorber rear L & R | 2 | pcs | |
| Fuel filter | 2 | pcs | |
| Oil Filter | 2 | pcs | |
| Air cleaner | 2 | pcs | |
| MITSUBISHI L300 (H1-6441/B0-J056), Year Model: 2017 Engine No.: 4D56AAR4546 | | | |
| Ball joint upper | 2 | pcs | |
| Ball joint lower | 2 | pcs | |
| Tire patch 50mm | 2 | box | |
| Glow plug | 4 | pcs | |
| HINO DUMPTRUCK H3-6626 (ZF-7614), Year Model: 2016, Engine No.: J08EUD26953 | | | |
| Fan belt | 2 | pcs | |
| Aircon fan belt | 1 | рс | |
| Shock absorber front L & R | 2 | pcs | |
| Oil filter | 2 | pcs | |
| Fuel filter | 2 | pcs | |
| AIR CLEANER ELEMENT PRIMARY & SECONDARY | 2 | PCS | |

| FOTON DUMPTRUCK SLF-129 (H3-6562), Year Model:2013, Engine No.: PHASER210T1-HC50736YA17 | | | |
|--|-----|------|--|
| Cabin Wind breaker deflector | 1 | рс | |
| Clutch booster repair kit | 1 | set | |
| Fan belt | 2 | pcs | |
| Cab roof light 24V | 2 | pcs | |
| Headlight Left & Right 24V | 1 | assy | |
| Rain visor front | 2 | pcs | |
| Sun visor | 2 | pcs | |
| Shock absorber front | 2 | pcs | |
| Seat cover (Re-uphositery) | 1 | serv | |
| Brake lining front with revets | 1 | set | |
| Brake lining rear with revets | 1 | set | |
| AIR CLEANER ELEMENT PRIMARY & SECONDARY | 3 | PCS | |
| Oil filter | 2 | pcs | |
| Fuel filter | 2 | pcs | |
| Door inner guard board Left & Right | 2 | assy | |
| Signal light Left & Right | 2 | pcs | |
| SDLG Motorized Road Grader G9138 SN:600287, Engine No. 6P18C011767 | | | |
| AIR CLEANER ELEMENT PRIMARY & SECONDARY | 1 | рс | |
| Fuel filter | 2 | pcs | |
| Cutting edge (11 holes) | 10 | set | |
| Flow bolt | 120 | pcs | |
| Oil Filter | 2 | pcs | |
| SDLG Backhoe Loader, Year Model: 2015, Engine No.: 4B15H800247 | | | |
| Cross-joint Spider # 4110001922072 | 4 | pcs | |
| Cross-joint retaining ring # 4110001922074 | 16 | pcs | |
| Transmission shaft O- ring #4110000076268 (shaft 1)-19 | 1 | рс | |
| Transmission shaft sealing ring #4110007921037(shaft 1)-21 | 1 | рс | |
| Transmission shaft O-ring #411001923040(shaft 2)-1 | 1 | рс | |
| Transmission shaft sealing ring #4110001921107(shaft 2)-8 | 1 | рс | |
| Transmission shaft O- ring #4110001921108(shaft 2)-9 | 1 | рс | |
| Transmission shaft sealing ring #4110001921108(shaft 2)-11 | 2 | pcs | |
| Oil filter | 2 | pcs | |
| Fuel filter (4DR5) | 2 | pcs | |

| Air cleaner | 2 | pcs | | | | | |
|---|---|-----|--|--|--|--|--|
| Sealing kit #4120005017016 parts # | 1 | set | | | | | |
| Total Amount in Figures Php: | | | | | | | |
| Total Amount in Words: | | | | | | | |
| The awarding for this RFQ will be on a lump-sum basis. Prospective Suppliers must quote for all of the name. Otherwise , they will be subjected for disqualification. | Please specify brand name otherwise, bids will not be accepted. | | | | | | |
| Brand and Model | | | | | | | |
| Delivery Period | | | | | | | |

After having carefully read and accepted your General Conditions, 1 / We quote you on the item(s) at prices note above. If the space for Delivery Period, Warranty and Price Validity are left blank, it means that I concur with the Terms and Conditions specified by DPWH.

c/o TEODY R. GALANG

BAC Chairperson DPWH, South Cotabato 1st DEO, General Santos City

Printed Name / Signature / Date

Tel. No. / Cellphone No. / E-mail Address

Page 5 of 5